

## EAST Search History

| Ref # | Hits  | Search Query   | DBs                                    | Default Operator | Plurals | Time Stamp       |
|-------|-------|--|--|------------------|---------|------------------|
| S1    | 0     | fail\$safe near6 clock near6 switch\$over            | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR               | OFF     | 2006/09/21 18:36 |
| S2    | 33477 | clock near6 (switch\$over switch switching switches) | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR               | OFF     | 2006/09/20 14:54 |
| S3    | 320   | clock near6 (switch\$over )                          | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR               | OFF     | 2006/09/20 14:55 |
| S4    | 4391  | 713/400-601.ccls.                                    | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR               | OFF     | 2006/09/20 14:55 |
| S5    | 33    | S3 and S4  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR               | OFF     | 2006/09/20 15:32 |
| S6    | 1     | "6292045".pn.  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR               | OFF     | 2006/09/20 15:07 |
| S7    | 20807 | micro\$controller near10 (cpu processor)             | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR               | OFF     | 2006/09/20 15:39 |
| S8    | 65829 | (first primary master) near3 clock                   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR               | OFF     | 2006/09/20 15:29 |
| S9    | 66    | S7 same S8   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR               | OFF     | 2006/09/20 15:40 |
| S10   | 12    | S2 and S9  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR               | OFF     | 2006/09/20 15:29 |
| S11   | 4     | S9 and S4  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR               | OFF     | 2006/09/20 15:40 |

## EAST Search History

|     |        |  |  |    |     |                  |
|-----|--------|--|--|----|-----|------------------|
| S12 | 91499  | (micro\$controller micro\$processor)<br>near10 (cpu processor)   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/20 15:40 |
| S13 | 120671 | (micro\$controller micro\$processor)<br>same (cpu processor)   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/20 15:40 |
| S14 | 627    | S13 same S8  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/20 15:40 |
| S15 | 70     | S14 and S4   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/20 15:41 |
| S16 | 8      | zilog\$.as. and S2   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/20 16:50 |
| S17 | 1      | "6845454".pn.  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 10:55 |
| S18 | 29     | (disabling near6 (detection<br>detector)) and 713/300-340.ccls.  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 17:35 |
| S19 | 13     | ((disabling near6 (detection<br>detector)) same clock) and<br>713/300-340.ccls.                            | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 17:37 |
| S20 | 20     | ((((power\$3 near3 (down off)) near6<br>(detection detector)) same clock)<br>and 713/300-340.ccls.         | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 17:52 |
| S21 | 83     | (((((power\$3 turn\$3) near3 (on up))<br>near6 (oscillator dll pll clock)) same<br>(fail\$3))              | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 19:15 |
| S22 | 32     | (((((power\$3 turn\$3) near3 (on up))<br>near6 (oscillator dll pll clock))<br>near10 (fail\$3))            | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 17:55 |
| S23 | 33     | (((((power\$3 turn\$3) near3 (on up))<br>near6 (oscillator dll pll clock))<br>near10 (fail\$3 inadequate)) | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 19:30 |

## EAST Search History

|     |      |   |  |    |     |                  |
|-----|------|---|--|----|-----|------------------|
| S24 | 83   | (((((power\$3 turn\$3) near3 (on up)) near6 (oscillator dll pll clock)) same (fail\$3)))              | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 18:37 |
| S25 | 33   | (((((power\$3 turn\$3) near3 (on up)) near6 (oscillator dll pll clock)) near10 (fail\$3 inadequate))) | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 18:37 |
| S26 | 51   | S24 not S25   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 18:39 |
| S27 | 84   | (((((power\$3 turn\$3) near3 (on up)) near6 (oscillator dll pll clock)) same (fail\$3 inadequate)))   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 18:39 |
| S28 | 51   | S27 not S25   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 18:39 |
| S29 | 5318 | (oscillator dll pll clock) near6 (fail\$3 inadequate)   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 18:42 |
| S30 | 32   | S29 near10 ((power\$3 turn\$3) near3 (on up))   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 18:45 |
| S31 | 57   | S29 and 713/300-340.ccls.   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 18:43 |
| S32 | 243  | S29 and (((power\$3 turn\$3) near3 (on up)) near6 (oscillator dll pll clock))                         | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 18:46 |
| S33 | 49   | S29 same (((power\$3 turn\$3) near3 (on up)) near6 (oscillator dll pll clock))                        | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 18:46 |
| S34 | 2259 | (((((power\$3 turn\$3) near3 (on up)) near6 (clock\$3)))  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 19:15 |
| S35 | 102  | S34 near10 (detect\$3 discover\$3)  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 19:22 |

## EAST Search History

|     |      |  |  |    |     |                  |
|-----|------|--|--|----|-----|------------------|
| S36 | 4    | S35 near10 (fail\$3 inadequate lost<br>unsuccess\$)  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 19:33 |
| S37 | 34   | (((((power\$3 turn\$3) near3 (on<br>up)) (power near2 applied)) near6<br>(oscillator dll pll clock)) near10<br>(fail\$3 inadequate)) | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 19:31 |
| S38 | 3255 | ( ((power\$3 turn\$3) near3 (on up))<br>(power near2 applied) ) near6<br>(clock\$)   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 19:33 |
| S39 | 32   | S38 near10 (fail\$3 inadequate lost<br>unsuccess\$)  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/21 19:33 |
| S40 | 699  | ((((power\$3 turn\$3) near3 (on up))<br>near10 (back\$up)) near10 (fail\$3<br>inadequate)  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:09 |
| S41 | 5360 | 713/300-340.ccls.  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:07 |
| S42 | 24   | S40 and S41  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:10 |
| S43 | 195  | ((((power\$3 turn\$3) near3 (on up))<br>near10 (memory DRAM RAM))<br>near10 (fail\$3 inadequate)                                     | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:12 |
| S44 | 6    | S43 and S41  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:10 |
| S45 | 5    | ((((power\$3 turn\$3) near3 (on up))<br>near10 (only near6 (necessary<br>needed required))) near10 (fail\$3<br>inadequate)           | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:14 |
| S46 | 398  | (((((power\$3 turn\$3) near3 (on up))<br>enabl\$3) near6 (deivce back\$up))<br>near10 (needed necessary<br>required)                 | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:28 |
| S47 | 67   | S46 same (fail\$ inadequate)   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:16 |

## EAST Search History

|     |       |   |  |    |     |                  |
|-----|-------|---|--|----|-----|------------------|
| S48 | 32    | S46 near10 (fail\$ inadequate)  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:28 |
| S49 | 17979 | ((fail\$ inadequate) near6 (primary master))  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:28 |
| S50 | 16599 | ((((power\$3 turn\$3) near3 (on up)) enabl\$3) near6 (secondary back\$up))  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:32 |
| S51 | 428   | S49 same S50  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:29 |
| S52 | 199   | S49 near10 S50  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:33 |
| S53 | 55    | S52 and clock   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:32 |
| S54 | 4     | S52 near10 clock  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:29 |
| S55 | 5745  | ((power\$3 turn\$3) near3 (on up)) near6 (secondary back\$up)   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:44 |
| S56 | 62    | S49 near10 S55  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:35 |
| S57 | 977   | ((power\$3 turn\$3) near3 (on up)) near6 (secondary back\$up) near10 (fail\$3 inadequate needed necessary required) | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:34 |
| S58 | 56    | S49 near10 S57  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:35 |
| S59 | 2     | S58 near10 clock  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:44 |

## EAST Search History

|     |     |   |  |    |     |                  |
|-----|-----|---|--|----|-----|------------------|
| S60 | 54  | ((power\$3 turn\$3) near3 (on up))<br>near6 ((secondary back\$up) near3<br>clock)   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:46 |
| S61 | 2   | S60 and 713/300-340.ccls.   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:45 |
| S62 | 0   | ((power\$3 turn\$3) near3 (on up))<br>near6 ((secondary back\$up) near3<br>clock)) same ((failure inadequate)<br>near3 (sensed detected))   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:46 |
| S63 | 0   | ((power\$3 turn\$3) near3 (on up))<br>near6 ((secondary back\$up) near3<br>clock)) same ((fail\$3 inadequate)<br>near3 (sensed detected))   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:46 |
| S64 | 0   | ((power\$3 turn\$3) near3 (on up))<br>near6 ((secondary back\$up) near3<br>clock\$)) same ((fail\$3 inadequate)<br>near3 (sensed detected)) | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:47 |
| S65 | 5   | ((power\$3 turn\$3) near3 (on up))<br>near6 ((secondary back\$up) near3<br>clock\$)) near10 (fail\$3 inadequate)                            | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:58 |
| S66 | 2   | ((power\$3 turn\$3) near3 (on up))<br>near6 ((secondary back\$up) near3<br>clock\$)) and 713/300-340.ccls.                                  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:58 |
| S67 | 2   | ((power\$3 turn\$3) near3 (on up))<br>near6 ((slave secondary back\$up)<br>near3 clock\$)) and 713/300-340.<br>ccls.                        | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:58 |
| S68 | 74  | ((power\$3 turn\$3) near3 (on up))<br>near6 ((slave secondary back\$up)<br>near3 clock\$))  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 08:59 |
| S69 | 5   | ((power\$3 turn\$3) near3 (on up))<br>near6 ((slave secondary back\$up)<br>near3 clock\$)) near10 (fail\$3<br>inadequate)                   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:00 |
| S70 | 18  | ((power\$3 turn\$3) near3 (on up))<br>near6 ((slave secondary back\$up)<br>adj2 clock\$))   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:09 |
| S71 | 711 | ((power\$3 turn\$3) near3 (on up))<br>near6 (slave secondary back\$up))<br>near10 (fail\$3 inadequate)                                      | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:12 |

## EAST Search History

|     |       |   |  |    |     |                  |
|-----|-------|---|--|----|-----|------------------|
| S72 | 25    | S71 and 713/300-340.ccls.   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:10 |
| S73 | 8     | (((power\$3 turn\$3) near3 (on up))<br>near6 (slave secondary back\$up))<br>near10 (only near (needed<br>necessary required)) | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:11 |
| S74 | 1916  | (((power\$3 turn\$3) near3 (down<br>off))) near10 (unneeded<br>unnecessary)   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:20 |
| S75 | 30727 | after near6 (back\$up secondary)  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:17 |
| S76 | 0     | S74 near10 S75  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:16 |
| S77 | 1     | S74 same S75  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:16 |
| S78 | 45    | (((power\$3 turn\$3) near3 (down<br>off))) near10 (unneeded<br>unnecessary)) near10 (fail\$3<br>inadequate)                   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:43 |
| S79 | 816   | power near6 shed\$4   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:31 |
| S80 | 4     | S79 near10 (unneeded<br>unnecessary)  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:36 |
| S81 | 19    | S79 and 713/300-340.ccls.   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:37 |
| S82 | 85    | S79 near10 (\$needed \$necessary<br>required)   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:39 |
| S83 | 3     | S82 and 713/300-340.ccls.   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:37 |

## EAST Search History

|     |         |   |  |    |     |                  |
|-----|---------|---|--|----|-----|------------------|
| S84 | 82      | S82 not S81   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:38 |
| S85 | 82      | S82 not S81 not S83   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:41 |
| S86 | 0       | (S79 near10 (\$needed \$necessary required)) same ((after follow\$3) near3 (fail\$3 inadequate))  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:40 |
| S87 | 18      | (S82 not S81 not S83) and g06f\$  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:41 |
| S88 | 1710    | (((((power\$3 turn\$3) near3 (down off))) near10 (\$needed \$necessary required)) near10 (after)  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:43 |
| S89 | 217     | (((((power\$3 turn\$3) near3 (down off))) near10 (\$needed \$necessary required)) and ((back\$up secondary) near10 (((power\$3 turn\$3) near3 (on up)) near10 (back\$up)))  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:45 |
| S90 | 14      | (((((power\$3 turn\$3) near3 (down off))) near10 (\$needed \$necessary required)) same ((back\$up secondary) near10 (((power\$3 turn\$3) near3 (on up)) near10 (back\$up))) | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:47 |
| S91 | 24620   | (((((power\$3 turn\$3) near3 (down off))) near10 (\$needed \$necessary required))   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:47 |
| S92 | 8322    | (((((power\$3 turn\$3) near3 (down off))) near10 (primary master))  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:47 |
| S93 | 3873209 | (\$needed \$necessary required) (after near6 fail\$3)   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:48 |
| S94 | 188     | S92 near10 S93  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:48 |



## EAST Search History

|          |     |   |  |    |     |                  |
|----------|-----|---|--|----|-----|------------------|
| S95      | 4   | S94 and 713/300-340.ccls.   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:49 |
| S96      | 25  | S94 and g06f\$  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 09:49 |
| S97      | 201 | (((power\$3 turn\$3) near3 (on up))<br>near10 (secondary back\$up))<br>near10 (needed necessary)                                  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 11:03 |
| S98      | 9   | S97 and "713".clas.   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 11:01 |
| S99      | 13  | (((power\$3 turn\$3) near3 (on up))<br>near10 (secondary back\$up))<br>near10 ((needed necessary) near3<br>only)                  | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 11:03 |
| S10<br>0 | 16  | (((power\$3 turn\$3) near3 (on up))<br>near10 (secondary back\$up))<br>near10 ((needed necessary<br>required) near3 only)         | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 11:04 |
| S10<br>1 | 347 | (((power\$3 turn\$3) near3 (on up))<br>near10 (secondary back\$up))<br>near10 (needed necessary<br>required)                      | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 11:08 |
| S10<br>2 | 59  | S101 and g06f\$   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 11:09 |
| S10<br>3 | 63  | (((power\$3 turn\$3) near3 (on up))<br>near10 (secondary back\$up))<br>near10 ((fail\$3 inadequate) near6<br>(detect\$3 sens\$3)) | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 11:08 |
| S10<br>4 | 12  | S103 and g06f\$   | US-PGPUB;<br>USPAT;<br>EPO;<br>IBM_TDB | OR | OFF | 2006/09/22 11:09 |